



## Packaging Information



Dimensions in Millimeters

## Core Loss

### Irms DERATING WITH CORE LOSS



## Inductance Characteristics

### Inductance vs. Idc

